



Uses:

- Removing iron and rust from paint
- Removing Tar and sap from paint
- Cleaning brake dust from wheels
- Removing Wax residue

Instructions for use:

Optimum Ferrex is a non acid, thiol based liquid used to safely remove rust and tar from all automotive surfaces.

- Always wear gloves and protective eyewear when working with Ferrex.
- Ensure that all surfaces are cool to the touch before application of Ferrex
- Rinse off heavy dust and dirt using a pressure washer.
- Sparingly apply Ferrex to the surface to be treated, allow to dwell 2-5 minutes, but not dry.
- Agitate with a soft brush or microfiber towel dampened with Optimum No Rinse.
- Thoroughly rinse to remove all traces (seen as a red liquid) of Ferrex.
- Continue with your wash process as normal.

Optimum Ferrex™

is a thiol based iron
and tar contamination
dissolver and
remover.

